



CONNELLY DRILLING SAFETY TEAMS

RULES OF PPE

SHOP

Steel toe boots at all times: Unless walking through designated safe zone. The zone extends from the break room door to the shop to the door leading to the front office area. This zone is identified with tape placed on the floor.

While using:

- Grinding Wheel: Protective safety glasses and gloves
- Torches: Tinted protective glasses
- Pressure Washer: Leather work gloves
- Forklift: Must wear seatbelt

JOBSITE

Steel toe boots: At all times. Zero exceptions.

Hard hat: When overhead hazards are present. Within 10' of fall zone from tower of rig. Check your hard hat for the expiration date. If it has expired pick up new hard hat from Danny.

Gloves: Required when handling drill tooling or steel.

Hi Vis Shirts/Sweatshirts/Jackets: When working in urban or traffic areas.

Hearing Protection: Required when working on air rotary rigs when decibel levels exceed 80 dB for a consistent period of time.

Dust Mask: Geothermal grout crew.

Splash Proof Goggles/Protective Sleeves: Geothermal tie in crew using heating iron.



CONNELLY DRILLING SAFETY TEAMS

Safety Violations: \$25 decrease from individual's safety bonus.

- 1) Any time an individual is seen not following the rules of PPE in the shop or on a jobsite.
- 2) Any DOT violation received. Vehicle compliance to DOT is the driver's responsibility.

Safety Bonus: \$25 increase to individual's safety bonus.

- 1) Pass a site safety inspection. This requires the following:
 - a. Utilities ticket is clear and utilities are marked/identified.
 - b. Wearing proper PPE.
 - c. Organized work area, free of trip hazards.
 - d. Work process on rig follows safety protocol. Ex: hands not touching auger during rotation.
 - e. Truck and rig toolboxes are organized and clean. DOT daily inspection book has been completed to date.
- 2) Passing a DOT inspection.